





as of 09/96

33-04-003 , Instrument Cluster






33-04-004 , Instrument Cluster




33-04-005 , Instrument Cluster









33-04-006 , Instrument Cluster

Vehicle Speed Sensor






33-04-007 , Instrument Cluster






2,9 L V6 12V as of 03/96 2,9 L V6 24V as of 03/96 all others as of 03/96 2,9 L V6 12V before 03/96 2,9 L V6 24V before 03/96 all others before 03/96






33-04-008 , Instrument Cluster , Auxiliary warning Trip computer




before 03/96 2,9 L V6 12V before 03/96 as of 03/96 2,9 L V6 12V as of 03/96 TCI Diesel as of 09/96




automatic transmis-
sion




33-04-009 , Instrument Cluster , Auxiliary warning








33-04-010 , Instrument Cluster , Auxiliary warning





33-04-011 , Instrument Cluster , Auxiliary warning





33-04-012 , Instrument Cluster , Trip computer

